

Visual Rack Safety Audit Report No: 1349

Conducted On 3/09/2020 by Nathan Burke



Storage Ideas Pty Ltd

27 Ash Road Prestons NSW 2170

Phone: (02) 9731-7999

Site: XXXX

Aisles Obstructed?

Racks Loaded?

Disclaimer: a) As rack inspections are generally carried out from floor level with racks loaded, Storage Ideas accepts no responsibility or liability for the structural integrity and/or faults/defects not sighted due to racks being loaded and/ or visually obstructed at the time of inspection. b) It is the client's responsibility to ensure all recommendations contained herein are carried out on a timely basis to ensure the ongoing safety of the pallet racking. c) The possibility exists that some undetected components in this installation may be "counterfeit brand". The presence of "counterfeit brand" components in the installation (known or unknown) renders the Racking Installation as "Non Conforming" and "Unsafe". NB The structural integrity of any rack can only be ascertained if the rack is fully unloaded.

AREA	RACK NO	BAY LOC	LEVEL	POSITION	PRODUCT	DAMAGE LVL	ISSUE	ACTION	QTY	COMMENTS
WH8	A	5		FRONT L/H	UPRIGHT COLBY 5475 19RF	ORANGE	DAMAGED	STRAIGHTEN	1	AT BASE
	B	1	1	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	C	1	1	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	C	2	2	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	C	3	1	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	C	5		REAR L/H	UPRIGHT COLBY 5475 15RF	ORANGE	DAMAGED	STRAIGHTEN	1	RETURN FLANGE
	D	1	1	FRONT	BEAM COLBY 2590X100	GREEN	DENTED	MONITOR		MONITOR
	D	4	2	FRONT L/H	CLIP COLBY BEAM	RED	DISLODGED	REFIT	1	
	D	5	1	FRONT	BEAM COLBY 1370X075	RED	DAMAGED	REPLACE	1	
	E	2	1	FRONT	BEAM COLBY 2590X100	GREEN	DENTED	MONITOR		MONITOR
	F	2	2	FRONT	BEAM COLBY 2590X100	ORANGE	DENTED	MONITOR		MONITOR
	F	1	1	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	G	1	1	FRONT	BEAM COLBY 1370X075	RED	DAMAGED	REPLACE	1	
	G	2	1	FRONT	BEAM COLBY 2590X100	RED	DAMAGED	REPLACE	1	
	H	2		FRONT L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	H	5	1	FRONT L/H	BASEPLATE COLBY HD LOW 2 HOLE	RED	DAMAGED	REPLACE	1	
	I	3		FRONT L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	K	1		REAR R/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	K	6		FRONT R/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	K	10		FRONT L/H	UPRIGHT COLBY 3675 15RF	ORANGE	DAMAGED	SPLICE		
	K	11		REAR L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	L	7		FRONT L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	L	6		REAR L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	STRAIGHTEN	1	
	L	2		FRONT L/H	UPRIGHT COLBY 3675 15RF	RED	DAMAGED	REPLACE	1	
	L	1		REAR L/H	BASEPLATE COLBY HD LOW 2 HOLE	RED	DAMAGED	REPLACE	1	